


BMW X3: 1FWU992

Vinnumber:	WBAWY110000C53195	Versionname:	X3 sDrive18 136PK Aut.
First Registrationdate:	21/11/2013	Fiscalpower:	
Expertise Mileage:	78673	Power Kw:	100
Bodytype:		Body color:	Gold
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3329
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/17/9 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 6 mm	Fr.R.	Pirelli: 6 mm
	Re.L.	Toyo: 6 mm	Re.R.	Toyo: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			464,72
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00





Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

