


**BMW 3: 1GK214**

Vinnumber:	<b>WBA3K91000F933515</b>	Versionname:	<b>3 TOURING 316d 116PK</b>
First Registrationdate:	<b>17/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>97012</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4502</b>
Maintenance:	<b>OVER 1700KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Steering wheel multifunctional	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 H Steel</b>			
Winter tyres:	Fr.L.	<b>Semperit: 4 mm</b>	Fr.R.	<b>Semperit: 4 mm</b>
	Re.L.	<b>Semperit: 4 mm</b>	Re.R.	<b>Semperit: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	30,00
-------------------	-------

Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Wheel cover F R, Damaged, E - Replace	30,00
---------------------------------------	-------



Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

*No pictures to display*