



BMW X1: 1EGP463			
Vinnumber:	<b>WBAVY11030VW87073</b>	Versionname:	<b>X1 sDrive16 116PK</b>
First Registrationdate:	<b>27/11/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>126210</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>6000 KM</b>	Parking lot:	<b>1228</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Panoramic roof
GPS storage	Central consol F
GPS storage <b>HD</b>	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting <b>Headlighting Halogen</b>	
Type of GPS <b>GPS big screen color</b>	
Type of Lining <b>Lining fabrics</b>	
Adaptive cruise control	

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
Winter tyres:	<b>205/50/17/94 H Steel</b>			
	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Dunlop: 6 mm</b>	Re.R.	<b>Dunlop: 6 mm</b>

Assistance equipment	
Repair kit	<b>Yes</b>
Compressor	<b>Yes</b>
Total cost ex VAT	<b>1218,60</b>
Wheel cover R L, Scratch(es), E - Replace	<b>30,00</b>



Wheel cover F R, Scratch(es), E - Replace	<b>30,00</b>
---	--------------



Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Bump(s), PDR - Knock out without painting 63,00



Wing F L, Bump(s), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Door frame R R, Scratch(es), 67 - Polish 55,19

