


BMW 3: 1GQH813

Vinnnumber:	WBA3Y11090D376292	Versionname:	3 GRAN TURISMO 318dA
First Registrationdate:	1/04/2014	Fiscalpower:	136PK Aut.
Expertise Mileage:	145089	Power Kw:	100
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4531
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	25/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			409,80
Door R R, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Ignition key, Incomplete, E - Replace			150,00
<i>No pictures to display</i>			
Seat cover F L, Tear, Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)			259,80



Tailgate, Bad repair, Acceptable 0,00

