


**BMW SERIE 3 GRAN TURISMO: 1GCY877**

|                                    |                          |              |                  |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber:                         | <b>WBA3Y11090D448057</b> | Versionname: | <b>318d</b>      |
| First Registrationdate:            | <b>3/01/2014</b>         | Fiscalpower: |                  |
| Expertise Mileage:                 | <b>119989</b>            | Power Kw:    | <b>100</b>       |
| Bodytype:                          |                          | Body color:  | <b>Blue</b>      |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>   |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b> |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>        |
| Maintenance:                       | <b>IN 2800 KM</b>        | Parking lot: | <b>2214</b>      |
| Maintenance:                       | <b>OK</b>                |              |                  |
| Battery functioning:               | <b>Yes</b>               |              |                  |
| Number of doors:                   | <b>5</b>                 |              |                  |
| Number of seats:                   | <b>5</b>                 |              |                  |
| Number head rests:                 | <b>5</b>                 |              |                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                  |
| Category:                          | <b>Passenger Car</b>     |              |                  |
| Oil level:                         | <b>OK</b>                |              |                  |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                  |

**Options**

|                                |                                  |                      |
|--------------------------------|----------------------------------|----------------------|
| Radio CD                       |                                  | Central consol F     |
| GPS storage                    | <b>HD</b>                        | Luggage cover        |
| GPS storage                    |                                  | Rear parking sensors |
| Windows electric F             |                                  |                      |
| Windows electric R             |                                  |                      |
| Cruise Control                 |                                  |                      |
| Steering wheel multifunctional |                                  |                      |
| Radio multimedia               |                                  |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>      |                      |
| Type of GPS                    | <b>GPS big screen color</b>      |                      |
| Type of Lining                 | <b>Lining artificial leather</b> |                      |
| Type of climate control        | <b>Autom climate control</b>     |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                   |                       |       |                       |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
|               | <b>225/55/17/101 V LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                             | <b>Goodyear: 6 mm</b> | Fr.R. | <b>Goodyear: 6 mm</b> |
|               | Re.L.                             | <b>Toyo: 6 mm</b>     | Re.R. | <b>Toyo: 6 mm</b>     |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

 Total cost ex VAT 1169,24

 Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00




Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 259,80



Door R R, Bad repair, P - Check 0,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, P - Check 0,00



Door panel R R, Damaged, Smart repair 110,64



Headlight R, Scratch(es), E - Replace 396,00



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 307,80



