



OPEL Insignia: 1GHX521

Vinnumber:	WOLGM8E5E1076244	Versionname:	INSIGNIA BRE ecoFLEX Edition 140PK
First Registrationdate:	12/02/2014	Fiscalpower:	
Expertise Mileage:	160337	Power Kw:	103
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2622
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Sun Roof electric
GPS storage	HD	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/98 MS LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	542,68
Seat cover F L, Damaged, Acceptable	0,00



Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------



Alloy rim R R, Rust, Acceptable	0,00
---------------------------------	------

No pictures to display

Sill outer R, Bump(s), LI - Repair and paint (complete)	310,50
---	--------



Alloy rim F L, Rust, Acceptable	0,00
---------------------------------	------

No pictures to display

Boot carpet, Stain, Cleaning	12,00
------------------------------	-------



Alloy rim F R, Rust, Acceptable	0,00
---------------------------------	------

No pictures to display