


**RENAULT Scenic: 1FCO231**

Vinnnumber:	<b>VF1JZ14K649042375</b>	Versionname:	<b>SCENIC Dynamique 110PK</b>
First Registrationdate:	<b>24/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>193936</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2432</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-artificial leather</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/96 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

	Compressor	<b>Yes</b>
Total cost ex VAT		0,00
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Rust, Acceptable		0,00



Seat cover F L, Tear, Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	