



**RENAULT MEGANE BERLINE: 1GMM587**

Vinnnumber:	<b>VF1BZ140649741915</b>	Versionname:	<b>1.5 ENERGY DCI 110 BOSE ? EDITION</b>
First Registrationdate:	<b>11/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>99107</b>	Power Kw:	<b>81</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2705</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/50/17/93 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Vredestein: 2 mm</b>	Fr.R.	<b>Vredestein: 2 mm</b>
	Re.L.	<b>Vredestein: 3 mm</b>	Re.R.	<b>Vredestein: 3 mm</b>

**Assistance equipment**

Total cost ex VAT	1329,87
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Trunk lid covering R, Scratch(es), Smart repair 110,64



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bodywork, Not original part, Acceptable	0,00
---	------

*No pictures to display*


Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door panel R L, Damaged, E - Replace	114,00
--------------------------------------	--------

