


MERCEDES C: 1EGD098

| | | | |
|-------------------------|--------------------------|--------------|---|
| Vinnumber: | WDD2042011G046469 | Versionname: | C BRE 200 CDI BlueEFF. S&S 136PK |
| First Registrationdate: | 22/11/2012 | Fiscalpower: | |
| Expertise Mileage: | 96962 | Power Kw: | 100 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | NOT OK | Parking lot: | 3807 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | | Luggage cover |
| GPS storage | HD | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining semi-leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
| | 225/45/17/98 MS LightMetal | | | |
| Winter tyres: | Fr.L. | Bridgestone: 5 mm | Fr.R. | Bridgestone: 5 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 190,00 |
|-------------------|--------|

| | |
|-------------------------------------|------|
| Door panel F R, Damaged, Acceptable | 0,00 |
|-------------------------------------|------|



| | |
|-----------------------------------|------|
| Maintenance, Maintenance, Execute | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|-------|
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



| | |
|-------------------------------------|------|
| Seat cover F L, Damaged, Acceptable | 0,00 |
|-------------------------------------|------|



| | |
|--|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|--|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|

