


PEUGEOT 308: 1GQF882

Vinnnumber:	VF3LB9HPADS209499	Versionname:	308 BER Active 92PK
First Registrationdate:	1/04/2014	Fiscalpower:	
Expertise Mileage:	98355	Power Kw:	68
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3528
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/94 V LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	969,16
-------------------	--------

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Seat cover F R, Stain, Cleaning	25,00
---------------------------------	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Seat cover F L, Stain, Cleaning	25,00
---------------------------------	-------



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

