


MERCEDES CLA: 1GPQ022

Vinnnumber:	WDD1173031N085789	Versionname:	CLA BER 220 CDI 163PK
First Registrationdate:	26/03/2014	Fiscalpower:	Aut.
Expertise Mileage:	45547	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3507
Maintenance:	B5 DANS 66 J		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Front parking sensors
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-leather
Type of climate control:	Autom climate control
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 968,00

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bodywork, Dirty, P - Check 0,00

No pictures to display

Ignition key, Incomplete, E - Replace 150,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper moulding R, Scratch(es), E - Replace 14,40



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

