



<b>RENAULT Clio: 1JGF621</b>			
Vinnumber:	<b>VF15R040H51837154</b>	Versionname:	<b>CLIO IV BER Business</b>
First Registrationdate:	<b>10/12/2014</b>	Fiscalpower:	<b>75PK</b>
Expertise Mileage:	<b>178537</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>Red</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3308</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>185/65/15/98 MS Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>562,00</b>
Front bumper, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bonnet, Stone chip(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wheel cover R R, Scratch(es), E - Replace			<b>24,00</b>



Wing R L, Scratch(es), LI - Repair and paint (complete)	<b>246,56</b>
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover F L, Damaged, E - Replace 24,00



Wheel cover F R, Damaged, E - Replace 24,00



Roof, Bump(s), Acceptable 0,00

*No pictures to display*

Engine protective plate, Tear, E - Replace 62,00



Seat cover R R, Stain, Forfeit 12,00



Wing R R, Bump(s), Acceptable 0,00

*No pictures to display*