


OPEL Astra: 1CDU120

Vinnnumber:	WOLPD8EA5C8015567	Versionname:	ASTRA BRE ecoFLEX Enjoy FAP 95PK
First Registrationdate:	27/10/2011	Fiscalpower:	
Expertise Mileage:	141217	Power Kw:	70
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2306
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	205/60/16/96 H Steel			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm


Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	669,88
Wheel cover F R, Scratch(es), E - Replace	30,00




Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Bump(s), LI - Repair and paint (complete)	301,68



Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Wing F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display