



MERCEDES VITO: 1PHJ203			
Vinnumber:	WDF63970313887181	Versionname:	116 CDI Pro A2
First Registrationdate:	8/08/2014	Fiscalpower:	
Expertise Mileage:	93550	Power Kw:	120
Bodytype:	Minibus	Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1306
Number of doors:	5		
Number of seats:	9		
Number head rests:	9		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	
Windows electric F	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/65/16/107 T Steel			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	1199,43
Bonnet, Stone chip(s), Acceptable	0,00

<i>No pictures to display</i>	
Tailgate, Bump(s), LI - Repair and paint (complete)	458,02



Internal Boot Lining L, Scratch(es), Smart repair	110,64
---	---------------



Roof, Hail damage, LI - Repair and paint (complete)	457,13
---	--------



Internal Boot Lining R, Scratch(es), Smart repair	110,64
---	--------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing F L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Sliding door R, Bump(s), Acceptable	0,00
-------------------------------------	------

No pictures to display