



PEUGEOT Expert: 1CUK539

Vinnnumber:	VF3XU9HM0BZ070476	Versionname:	EXPERT B/F MWB 229 L2H1 FAP(EU5)90PK
First Registrationdate:	1/03/2012	Fiscalpower:	
Expertise Mileage:	107513	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV19
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Type of headlighting:	Headlighting Halogen	Rear parking sensors:	
Type of Lining:	Lining fabrics	Type of Tow bar:	Tow bar fixed

Limited Technical Inspection

Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Power steering:	Yes
Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Wiper fluid level:	OK
Handbrake:	OK	Transmission:	OK
		Lighting:	OK
		Wiperblades:	OK

Degree of wear

	215/60/16/103 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
--------------	------------	-------	------------

Total cost ex VAT	865,37
--------------------------	---------------

Bumper R, Crack, Smart repair	110,64
--------------------------------------	---------------



Rear panel, Bump(s), Acceptable	0,00
--	-------------

No pictures to display

Bumper moulding R L, Missing, E - Replace	10,80
--	--------------



Bodywork, Not original part, Acceptable	0,00
--	-------------

No pictures to display

Outer door handle F R, Damaged, E - Replace	174,00
--	---------------



Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Roof, Damaged, LI - Repair and paint (complete)	361,13
---	--------

