


**RENAULT Grand Scenic: 1GIG477**

Vinnnumber:	<b>VF1JZ14P650210893</b>	Versionname:	<b>GRAND SCENIC Business 7pl.110PK</b>
First Registrationdate:	<b>14/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>148425</b>	Power Kw:	<b>81</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3227</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/96 H Steel</b>			
Winter tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>
Repair kit	<b>Yes</b>

Total cost ex VAT	1379,34
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80





Wheel cover F L, Missing, E - Replace 30,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Tailgate, Scratch(es), 67 - Polish 55,19



Seat cover F R, Stain, Cleaning 25,00



Rocker panel inner R L, Scratch(es), Acceptable 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 404,20



Wheel cover R R, Scratch(es), E - Replace 30,00



Bumper R, Hole, LI - Repair and paint (complete) 211,80





Door F L, Bump(s), PDR - Knock out without painting 63,00



Wheel cover F R, Scratch(es), E - Replace 30,00

