


VOLKSWAGEN Golf: 1GRY582

Vinnumber:	WVWZZZAUZEW318808	Versionname:	GOLF BER Trendline 90PK
First Registrationdate:	11/04/2014	Fiscalpower:	
Expertise Mileage:	155824	Power Kw:	66
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2331
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1384,90
-------------------	----------------

Wheel cover R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door panel F R, Missing, E - Replace	44,00
--------------------------------------	--------------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing F L, Chemical pollution, Acceptable	0,00
--	-------------

No pictures to display

Rear spoiler, Chemical pollution, I I - Repair and paint (complete)	115,56
---	---------------

Wheel cover F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Chemical polution, LI - Repair and paint (complete)		290,08
Roof, Chemical polution, LI - Repair and paint (complete)		481,50
Wheel cover R R, Scratch(es), E - Replace		30,00
Wing R R, Chemical polution, LI - Repair and paint (complete)		308,20
Windscreen, Stone chip(s), Windscreen repair		0,00
Bumper F L, Bump(s) and scratch(es), It - Spot repair		115,56