


TOYOTA Auris: 1GHH734

Vinnnumber:	SB1ZS3JE30E064005	Versionname:	AURIS TOUR.SP. HSD Comfort CVT 99PK Aut.
First Registrationdate:	7/02/2014	Fiscalpower:	
Expertise Mileage:	130173	Power Kw:	73
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	4303
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
GPS storage	HD
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	95,00
-------------------	-------

Covering interior front pillar L, Burned, Smart repair	0,00
--	------



Bumper corner R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Bad repair, Acceptable	0,00
----------------------------------	------



Door frame F R, Bump(s) and scratch(es), It - Spot repair 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Bad repair, Acceptable 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 0,00

