



TOYOTA AVENSIS: PBU006

Vinnumber:	SB1DW56L70E060704	Versionname:	
First Registrationdate:	3/06/2004	Fiscalpower:	
Expertise Mileage:	110048	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2115
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Bridgestone: 0 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	420,36
-------------------	---------------

Seat cover R L, Deformed, Acceptable	0,00
--------------------------------------	-------------



Wheel cover F R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper F L, Scratch(es), It - Spot repair	115,56
---	---------------



Roof, Scratch(es), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F L, Worn, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover R L, Unclashed, N - Mount/Dismount 0,00



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Strained , P - Check 0,00



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 30,00

