



VOLKSWAGEN TOURAN: 1AER822

Vinnumber:	WVGZZZ1TZDW081133	Versionname:	
First Registrationdate:	25/02/2013	Fiscalpower:	
Expertise Mileage:	203132	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4808
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	3497,94
Windscreen, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80





Air vent R M, Damaged, E - Replace 244,00



Backrest cover R L, Damaged, E - Replace 104,00



Bumper grille F R, Missing, E - Replace 32,40



Interior, Smell, Ozone treatment 152,58



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Front bumper, Damaged, Le - Replace and paint 735,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Tailgate, Chemical polution, LI - Repair and paint (complete) 301,68



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08

