



VOLKSWAGEN SHARAN: 1JXX991

Vinnnumber:	WVWZZZ7NZFV026498	Versionname:	2.0 CR TDI 103KW COMFORTLINE BMT
First Registrationdate:	16/03/2015	Fiscalpower:	
Expertise Mileage:	103516	Power Kw:	103
Bodytype:	MPV	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1610
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Other: 3 mm	Fr.R.	Other: 3 mm
	Re.L.	Other: 3 mm	Re.R.	Other: 3 mm

Assistance equipment

Total cost ex VAT	1412,01
Air vent R M, Broken, E - Replace	88,00



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	348,09
---	---------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Rocker panel inner R R, Bump(s), Acceptable	0,00
---	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Sill outer L, Scratch(es), LI - Repair and paint (complete)	372,60
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display