


RENAULT Scenic: 1GKI401

Vinnnumber:	VF1JZ14K650186519	Versionname:	SCENIC Energy Life 110PK
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	111334	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2128
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	900,44
-------------------	--------

Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------



Wheel cover F R, Scratch(es), E - Replace 30,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel cover R L, Scratch(es), E - Replace 30,00



Ceiling, Damaged, Smart repair 64,32



Door frame R L, Bump(s) and scratch(es), It - Spot repair 115,56



Seat cover R L, Stain, Cleaning 50,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R R, Bump(s) and scratch(es), It - Spot repair 115,56



Wheel cover R R, Scratch(es), E - Replace 30,00



Rear Panel Internal Lining, Scratch(es), Smart repair 110,64



Boot carpet, Waterinfiltration, P - Check 0,00



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Wheel cover F L, Scratch(es), E - Replace 30,00



Armrest R M, Damaged, E - Replace 87,00

