



| VOLKSWAGEN CC: ER0769 | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber: | WVWZZZ3CZEE538386 | Versionname: | CC 4M BMT DSG 177PK Aut. |
| First Registrationdate: | 28/05/2014 | Fiscalpower: | |
| Expertise Mileage: | 161752 | Power Kw: | 130 |
| Bodytype: | Berline | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metallic |
| Transmission: | 4 Weel | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2722 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | |
|--------------------------------|------------------------------|
| Radio CD | Sun Roof electric |
| GPS storage | Central consol F |
| GPS storage | Luggage cover |
| Windows electric F | Front parking sensors |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Seats F heated | |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|----------------------------------|--------------------------|-------|--------------------------|
| | 235/40/18/95 V LightMetal | | | |
| Winter tyres: | Fr.L. | Bridgestone: 5 mm | Fr.R. | Bridgestone: 5 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

| Assistance equipment | | | |
|--|------------|------------|----------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 2369,24 |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | | | 95,00 |



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre R L, Damaged, E - Replace 132,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre repair kit, Missing, E - Replace 210,53



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Bumper Trim F, Missing, E - Replace 20,00



Windscreen, Crack, E - Replace 487,20



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00





Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Tyre F R, Damaged, E - Replace 132,00

