



SKODA Octavia: AT1208			
Vinnnumber:	TMBJG9NE1E0202359	Versionname:	OCTAVIA COMBI Elegance
First Registrationdate:	24/04/2014	Fiscalpower:	105PK
Expertise Mileage:	88691	Power Kw:	77
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3423
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Seats electric F L
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of Lining:	Lining semi-leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			660,08
Bonnet, Chemical polution, LI - Repair and paint (complete)			290,08

	Rear window, Scratch(es), E - Replace	370,00
--	--	---------------

--	--	--



Door R L, Bad repair, Paint 0,00



Door F L, Bad repair, Paint 0,00

