



RENAULT Scenic: 1GKF459			
Vinnnumber:	VF1JZ14K650186510	Versionname:	SCENIC Energy Life 110PK
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	108803	Power Kw:	81
Bodytype:	Hatchback	Body color:	Light Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1506
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		




Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/60/16/92 V Steel			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Spare wheel	Yes

Total cost ex VAT	1077,12
Tailgate, Bump(s), PDR - Knock out without painting	63,00

		
Bumper R, Scratch(es), It - Spot repair		
115,56		



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Interior, Dirty, Cleaning 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete) 220,18



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18

