



VOLKSWAGEN TIGUAN: 1HBR434

Vinnnumber:	WVGZZ5NZEW601373	Versionname:	TIGUAN Sport & Style BM Tech.110PK
First Registrationdate:	12/06/2014	Fiscalpower:	
Expertise Mileage:	209835	Power Kw:	81
Bodytype:	SUV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3231
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Sun Roof electric
GPS storage	HD	Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/17/99 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 3 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1056,40
-------------------	----------------

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Windscreen, Crack, E - Replace	0,00
--------------------------------	-------------





Backrest cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Repaired, Acceptable 0,00

No pictures to display

Bumper moulding F R, Scratch(es), E - Replace 14,40



Door F L, Repaired, Acceptable 0,00

No pictures to display

Tyre F R, Flat, E - Replace 132,00



Door F R, Bump(s), Acceptable 0,00

No pictures to display

Rearview mirror L complete, Broken, Le - Replace and paint 283,00



Bumper R, Bump(s), E - Replace 415,20



Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display