


HYUNDAI i20: 1ACO670

Vinnnumber:	NLHB351PAGZ175472	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	15617	Power Kw:	
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	No	Parking lot:	3411
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting:	Headlighting Halogen		
Type of Lining:	Lining fabrics		
Type of climate control:	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	No
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	NOT OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	450,00
Registration Document, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Missing, E - Replace	150,00



Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

No pictures to display