



VOLVO V40: 1FAM091

Vinnumber:	YV1MV8481D2058902	Versionname:	V40 D2 Base 115PK
First Registrationdate:	7/05/2013	Fiscalpower:	
Expertise Mileage:	182543	Power Kw:	84
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2104
Maintenance:	9 MND 10125KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm











Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1386,75
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)			211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

		168,00
		95,00
		95,00
		25,00
		32,40
		211,80
		25,00
		318,35
		14,40
		95,00

