



VOLKSWAGEN Passat: 1FLJ294

Vinnnumber:	WVWZZZ3CZEE028999	Versionname:	PASSAT VAR Trendline BM
First Registrationdate:	6/08/2013	Fiscalpower:	105PK
Expertise Mileage:	125913	Power Kw:	77
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4325
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Panoramic roof
GPS storage	Central consol F
GPS storage HD	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting Headlighting Halogen	
Type of GPS GPS big screen color	
Type of Lining Lining fabrics	
Type of climate control Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V Steel			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	341,80
Bumper F R, Deformed, P - Check	0,00



Maintenance book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Sunroof cover, Not functioning (well), P - Check	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Bumper F L, Deformed, P - Check 0,00



Seat cover R L, Stain, Cleaning 100,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Armrest R M, Stain, Acceptable 0,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display