



**CITROEN Berlingo: 1GAI308**

Vinnumber:	<b>VF77J9HLODJ778970</b>	Versionname:	<b>BERLINGO 2PLC Exclusive</b>
First Registrationdate:	<b>5/12/2013</b>	Fiscalpower:	<b>115PK</b>
Expertise Mileage:	<b>206024</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2630</b>
Maintenance:	<b>IN 12300KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>HD</b> Rear parking sensors
Windows electric F	Type of Tow bar
Cruise Control	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>NOT OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>215/55/16/93 W Steel</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT	768,15		
Tyre R R, Worn, P - Check	0,00		



Seat cover F L, Stain, Cleaning	25,00
---------------------------------	-------



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Missing, E - Replace 30,00



Windscreen, Stone chip(s), Windscreen repair 58,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), P - Check 0,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Tyre R L, Worn, P - Check 0,00



Wing R R, Bump(s) and scratch(es), It - Spot repair 115,56



Dashboard, Scratch(es), Acceptable 0,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Wheel cover R R, Missing, E - Replace 30,00



Sill outer R, Scratch(es), Acceptable 0,00

*No pictures to display*

Rearlight L, Scratch(es), 67 - Polish 55,19



Door panel F L, Scratch(es), Acceptable 0,00

