



BMW SERIE 5 : 1KLX375

Vinnumber:	WBA5E51070G065676	Versionname:	520D
First Registrationdate:	29/05/2015	Fiscalpower:	
Expertise Mileage:	157491	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1113
Maintenance:	IN 17000 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1458,90
-------------------	----------------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------





Wing R L, Bad repair, P - Check 0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Stain, Cleaning 25,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00




Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door panel F L, Stain, Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Bumper R, Bump(s), LI - Repair and paint (complete) 254,16



Door R L, Bad repair, P - Check 0,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 430,02



Sill trim R, Scratch(es), LI - Repair and paint (partial) 0,00



Wing R R, Bump(s) and scratch(es), It - Spot repair 115,56



Seat cover F R, Stain, Acceptable 0,00

No pictures to display