



BMW X5: 1FXT820

Vinnnumber:	WBAKS410900C34887	Versionname:	X5 3.0dA xDrive30 258PK Aut.
First Registrationdate:	2/12/2013	Fiscalpower:	
Expertise Mileage:	67617	Power Kw:	190
Bodytype:	SUV	Body color:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3102
Number of doors:	7		
Number of seats:	7		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Steats R heated	
Windows electric F		Panoramic roof	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	255/50/19/107 W LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Total cost ex VAT	190,00
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bad repair, Acceptable	0,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door R R, Bad repair, Acceptable 0,00



Door F R, Bad repair, Acceptable 0,00



Wing F R, Bad repair, Acceptable 0,00



Roof, Bad repair, Acceptable 0,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00

