



BMW 5: 1GTA537

Vinnnumber:	WBA5N21060D496624	Versionname:	5 GRAN TURISMO 520dA
First Registrationdate:	22/04/2014	Fiscalpower:	163PK Aut.
Expertise Mileage:	112647	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2733
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats R heated	
Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Sun Roof electric	
Steering wheel multifunctional		Panoramic roof	
Seats F heated		Central consol F	
Type of headlighting	Headlighting LED	Luggage cover	
Type of GPS	GPS big screen color	Front parking sensors	
Type of Lining	Lining leather	Rear parking sensors	
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/19/102 W LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Total cost ex VAT	1236,41
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 348,09



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display