




<b>BMW X4: VF5594</b>			
Vinnnumber:	<b>WBAXX110400L95280</b>	Versionname:	<b>X4 xDrive20dA 190PK Aut.</b>
First Registrationdate:	<b>4/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>82056</b>	Power Kw:	<b>140</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4329</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Xenon</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>225/60/17/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>		<b>327,21</b>	
<b>Wing F R, Scratch(es), Acceptable</b>		<b>0,00</b>	
<i>No pictures to display</i>			
<b>Bonnet, Scratch(es), Acceptable</b>		<b>0,00</b>	
<i>No pictures to display</i>			
<b>Wing R R, Bump(s), Acceptable</b>		<b>0,00</b>	
<i>No pictures to display</i>			
<b>Door R L, Bump(s), PDR - Knock out without painting</b>		<b>63,00</b>	



<b>Bumper R, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)

264,21

