



2387.9
In
107763

MERCEDES A: 1FWB950			
Vinnnumber:	WDD1760121J200766	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	14/11/2013	Fiscalpower:	
Expertise Mileage:	107763	Power Kw:	80
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3532
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Kumho: 3 mm	Re.R.	Kumho: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	3636,01
Wing R L, Damaged, Le - Replace and paint	1231,51



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Wheel cover R R, Scratch(es), E - Replace	30,00
---	--------------



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Door F L, Bump(s) and scratch(es), Le - Replace and paint 1082,52



Rear window, Scratch(es), Acceptable 0,00
No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Bonnet, Scratch(es), Acceptable 0,00
No pictures to display

Spoiler R, Scratch(es), Acceptable 0,00
No pictures to display

Full screen GPS, Missing, E - Replace 800,00



Wheel cover F L, Scratch(es), E - Replace 30,00

