


**MERCEDES C: 1EPD602**

|                         |                          |              |   |
|-------------------------|--------------------------|--------------|---|
| Vinnumber:              | <b>WDD2042021G084692</b> | Versionname: | <b>C BRE 220 CDI BlueEFF. S&amp;S 163PK</b> |
| First Registrationdate: | <b>12/02/2013</b>        | Fiscalpower: |   |
| Expertise Mileage:      | <b>97517</b>             | Power Kw:    | <b>120</b>                                  |
| Bodytype:               | <b>Break</b>             | Body color:  | <b>Dark Blue</b>                            |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                              |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>                            |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                   |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>4115</b>                                 |
| Number of doors:        | <b>5</b>                 |              |   |
| Number of seats:        | <b>5</b>                 |              |   |
| Number head rests:      | <b>5</b>                 |              |   |
| Rims summer:            | <b>Aluminium</b>         |              |   |
| Category:               | <b>Passenger Car</b>     |              |   |
| Oil level:              | <b>OK</b>                |              |   |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining semi-leather</b>   |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/45/17/91 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Bridgestone: 6 mm</b> | Fr.R. | <b>Bridgestone: 6 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b>    | Re.R. | <b>Michelin: 4 mm</b>    |

**Assistance equipment**

|                       |            |      |            |
|-----------------------|------------|------|------------|
| Emergency spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-----------------------|------------|------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 318,35 |
|-------------------|--------|

|                                   |      |
|-----------------------------------|------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|  |      |
|--|------|
| Rearview mirror housing L, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|  |      |
|--|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Wing R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|  |      |
|--|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|  |      |
|--|------|
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*

|   |        |
|---|--------|
| Door R R, Bump(s), LI - Repair and paint (complete) | 318,35 |
|---|--------|

