


MERCEDES C: 1GEV454

Vinnnumber:	WDD2040021A932251	Versionname:	C BER 220CDI BE Edition Avantgarde 163PK
First Registrationdate:	20/01/2014	Fiscalpower:	
Expertise Mileage:	141501	Power Kw:	120
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2715
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2383,03
-------------------	---------

Wing R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Sill outer L, Hole, Le - Replace and paint	712,00
--	--------




Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Door F R, Bump(s), PDR - Knock out without painting

63,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Seat cover F L, Worn, P - Check

0,00



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)

301,68



Seat cover F L, Stain, Cleaning

25,00



Boot carpet, Damaged, P - Check

0,00



Mirror side blinker L, Waterinfiltration, P - Check

0,00



Front bumper, Bad repair, P - Check

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Door frame R L, Bump(s), Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

