



FORD S Max: 1EWW578

Vinnnumber:	WF0SXXGBWSDJ88505	Versionname:	S-MAX Econetic Titanium
First Registrationdate:	10/04/2013	Fiscalpower:	St&St DPF 115PK
Expertise Mileage:	104477	Power Kw:	85
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3824
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Compressor **Yes**

Total cost ex VAT	940,26
Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Damaged, Smart repair	110,64



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Sill outer R, Scratch(es), LI - Repair and paint (complete)

372,60



Front bumper, Stone chip(s), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete)

362,02



Wing R R, Repaired, Acceptable

0,00

No pictures to display