


MERCEDES A180: 1ECL942

Vinnumber:	WDD1760121J012729	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	19/10/2012	Fiscalpower:	
Expertise Mileage:	139099	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2830
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Front parking sensors
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1124,50
Wing R R, Scratch(es), LI - Repair and paint (complete)	332,20



Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Steering wheel, Worn, Acceptable	0,00



Bumper R, Bump(s), LI - Repair and paint (complete) 259,80



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Stone chip(s), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Remove lettering 75,00



Boot cover, Missing, E - Replace 50,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Worn, P - Check 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Stone chip(s), Acceptable 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Instruction book, Damaged, E - Replace 25,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Glove compartment lid, Incomplete, Repair/replace (lump sum) 2,50

