



FORD Mondeo: 1DVD982			
Vinnnumber:	WF0EXXGBBECE46517	Versionname:	MONDEO BER Titanium
First Registrationdate:	6/09/2012	Fiscalpower:	136PK
Expertise Mileage:	145864	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3524
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			3164,85
Front bumper, Scratch(es), LI - Repair and paint (complete)			211,80



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68
---	---------------



Door F L, Chemical polution, Acceptable 0,00

No pictures to display

Protection plate M, Tear, E - Replace 74,00



Wing R L, Scratch(es), Acceptable 0,00



Bumper R, Bump(s) and scratch(es), Le - Replace and paint 651,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing F L, Bump(s) and scratch(es), Le - Replace and paint 530,02




Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

No pictures to display

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 406,50



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display