



MERCEDES E: 1HFL161			
Vinnumber:	WDD2120051B053456	Versionname:	E BER 200CDI BE 136PK
First Registrationdate:	8/07/2014	Fiscalpower:	
Expertise Mileage:	189045	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/55/16/99 V LightMetal			
Winter tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			428,25
Alloy rim R L, Scratch(es), 1 - Repair			100,00





Alloy rim F L, Scratch(es), I - Repair 100,00



Rear bulkhead lining, Missing, E - Replace 12,69



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper moulding R, Scratch(es), Acceptable 0,00



Alloy rim F R, Scratch(es), I - Repair 100,00



GPS, Not functioning (well), P - Check 0,00



Boot carpet, Missing, Repair/replace (lump sum) 0,00



Door R L, Bump(s), Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

