


MERCEDES C: 1ERV932

| | | | |
|-------------------------|--------------------------|--------------|---|
| Vinnumber: | WDD2042001G096784 | Versionname: | C BRE 180 CDI BlueEFF. S&S 120PK |
| First Registrationdate: | 5/03/2013 | Fiscalpower: | |
| Expertise Mileage: | 88910 | Power Kw: | 88 |
| Bodytype: | Break | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | B OVER 50D | Parking lot: | 1311 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | |
|--------------------------------|---------------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | HD | Luggage cover |
| GPS storage | | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining semi-artificial leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|----------------------|-------|---------------------|
| | 225/45/17/91 H LightMetal | | | |
| Winter tyres: | Fr.L. | Pirelli: 3 mm | Fr.R. | Kleber: 3 mm |
| | Re.L. | Kleber: 5 mm | Re.R. | Kleber: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|--|--------------|
| Total cost ex VAT | 95,00 |
| Bodywork, Glue residues, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Seat cover F L, Stain, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|-----------------------------------|------|
| Door R R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |