

FORD Transit 300S: UP9164

Vinnnumber:	WF05XXBDFSCA34308	Versionname:	TRANSIT 300S MBUS SWB Silv.DPF(EU5)100PK
First Registrationdate:	25/04/2012	Fiscalpower:	
Expertise Mileage:	115781	Power Kw:	74
Bodytype:	Minibus	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2123
Number of doors:	5		
Number of seats:	9		
Number head rests:	9		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/70/15/104 R Steel			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 9 mm	Re.R.	Michelin: 9 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	738,52
-------------------	--------

Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing R R, Bad repair, Acceptable	0,00
----------------------------------	------



Rear Panel Internal Lining, Damaged, Smart repair	110,64
---	--------





Rearview mirror L complete, Damaged, E - Replace 138,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display


Trunk door R R, Bump(s), It - Spot repair 115,56




Trunk door R R, Missing, E - Replace 20,00



Door F R, Scratch(es), LI - Repair and paint (complete) 238,76



Trunk door R L, Bump(s), It - Spot repair 115,56



Interior, Dirty, Cleaning 0,00

No pictures to display