

**BMW 1: 1GDC569**

|                                    |                          |              |                                       |
|------------------------------------|--------------------------|--------------|---------------------------------------|
| Vinnnumber:                        | <b>WBA1C91040J519378</b> | Versionname: | <b>1 HATCH 116d Eff.Dyn.Ed. 116PK</b> |
| First Registrationdate:            | <b>6/01/2014</b>         | Fiscalpower: |                                       |
| Expertise Mileage:                 | <b>152324</b>            | Power Kw:    | <b>85</b>                             |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                           |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                        |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                      |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                             |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2615</b>                           |
| Number of doors:                   | <b>5</b>                 |              |                                       |
| Number of seats:                   | <b>5</b>                 |              |                                       |
| Number head rests:                 | <b>5</b>                 |              |                                       |
| Rims summer:                       | <b>Aluminium</b>         |              |                                       |
| Category:                          | <b>Passenger Car</b>     |              |                                       |
| Oil level:                         | <b>OK</b>                |              |                                       |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                       |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Sun Roof electric            |
| Windows electric F             | Central consol F             |
| Windows electric R             | Luggage cover                |
| Cruise Control                 | Front parking sensors        |
| Steering wheel multifunctional | Rear parking sensors         |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting LED</b>      |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |
| Sport seats                    |                              |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                 |                          |       |                          |
|---------------|---------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/5/16/91 T LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                           | <b>Michelin: 6 mm</b>    | Fr.R. | <b>Michelin: 6 mm</b>    |
|               | Re.L.                           | <b>Bridgestone: 4 mm</b> | Re.R. | <b>Bridgestone: 4 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 137,00 |
|-------------------|--------|

|   |       |
|---|-------|
| Roof, Bump(s), PDR - Knock out without painting | 63,00 |
|---|-------|



|                                     |      |
|-------------------------------------|------|
| Bumper F R, Scratch(es), Acceptable | 0,00 |
|-------------------------------------|------|

*No pictures to display*

|                                       |       |
|---------------------------------------|-------|
| Protection plate M, Tear, E - Replace | 74,00 |
|---------------------------------------|-------|

