


BMW 3: 1GTA534

Vinnumber:	WBA3L11060K176450	Versionname:	3 TOURING 320d
First Registrationdate:	22/04/2014	Fiscalpower:	Eff.Dyn.Ed. 163PK
Expertise Mileage:	124707	Power Kw:	120
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4706
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1142,47
Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	356,20








Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Door frame R L, Bump(s) and scratch(es), It - Spot repair	115,56
	
Door frame R R, Bump(s) and scratch(es), It - Spot repair	115,56
	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Ceiling, Stain, Cleaning	25,00
	
Alloy rim R R, Scratch(es), Acceptable	0,00
No pictures to display	