


OPEL Astra: 1DSW708

Vinnnumber:	WOLPD8EA5C8110758	Versionname:	ASTRA BRE ecoFLEX Enjoy
First Registrationdate:	16/08/2012	Fiscalpower:	150Ys DPF 95PK
Expertise Mileage:	162619	Power Kw:	70
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:		Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage		Rear parking sensors	
GPS storage	SD		
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H Steel			
Winter tyres:	Fr.L.	Other: 5 mm	Fr.R.	Other: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1118,53
-------------------	----------------

Rear spoiler, Bump(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	---------------




Outer door handle F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 30,00



Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wheel cover F R, Missing, E - Replace 30,00



Front bumper, Deformed, I - Repair 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

