

**BMW 3: 1GMV602**

Vinnumber:	WBA3K110X0F859490	Versionname:	3 TOURING 318dA 136PK
First Registrationdate:	13/03/2014	Fiscalpower:	Aut.
Expertise Mileage:	172318	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1211
Maintenance:	21000 KM OF 3:2019		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage	HD	Rear parking sensors	
GPS storage			
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1132,95
-------------------	----------------

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Bonnet, Bump(s), PDR - Knock out without painting 82,80



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Stone chip(s), P - Check 0,00



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35

