



AUDI A4: 1EZL413

Vinnumber:	WAUZZZ8K8DA238411	Versionname:	A4 AVANT TDie 136PK
First Registrationdate:	29/04/2013	Fiscalpower:	
Expertise Mileage:	165253	Power Kw:	100
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1315
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear













	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel **Yes**

Total cost ex VAT	979,89
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



		Bonnet, Bad repair, Acceptable	0,00	
			Rearlight L tailgate, Damaged, E - Replace	114,00
		Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18	
		Front bumper, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>				
		Wing F L, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>				
		Alloy rim F L, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>				
		Door F L, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>				
		Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35	
			Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
		Tailgate, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>				
		Door R L, Scratch(es), Acceptable	0,00	
<i>No pictures to display</i>				
		Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56	
