



TOYOTA Auris: 1GDZ647

Vinnnumber:	SB1ZS3JEX0E057214	Versionname:	AURIS TOUR.SP. HSD Comfort CVT 99PK Aut.
First Registrationdate:	13/01/2014	Fiscalpower:	
Expertise Mileage:	130452	Power Kw:	73
Bodytype:	Break	Body color:	Light Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1214
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm


Assistance equipment

Emergency spare wheel	Yes
-----------------------	------------

Total cost ex VAT	305,56
Sill outer L, Deformed, LI - Repair and paint (complete)	0,00



Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Interior, Dirty, Cleaning 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Rocker panel inner F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00

