


SKODA Superb: 1GUH283

| | | | |
|------------------------------------|--------------------------|--------------|--|
| Vinnnumber: | TMBJJ73T0E9052876 | Versionname: | SUPERB COMBI GreenLine Elegance 105PK |
| First Registrationdate: | 2/05/2014 | Fiscalpower: | |
| Expertise Mileage: | 76590 | Power Kw: | 77 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 4606 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|-----------------------------|-----------------------|--------------------------|
| Radio CD | | Seats R heated | |
| GPS storage | | Seats electric F L | |
| GPS storage | HD | Seats electric F R | |
| Windows electric F | | Sun Roof electric | |
| Windows electric R | | Panoramic roof | |
| Cruise Control | | Central consol F | |
| Steering wheel multifunctional | | Luggage cover | |
| Seats F heated | | Front parking sensors | |
| Type of headlighting | Headlighting Xenon | Rear parking sensors | |
| Type of GPS | GPS big screen color | Type of Tow bar | Tow bar removable |
| Type of Lining | Lining leather | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|---------------------|-------|---------------------|
| | 205/55/16/91 T LightMetal | | | |
| Winter tyres: | Fr.L. | Kleber: 5 mm | Fr.R. | Kleber: 5 mm |
| | Re.L. | Kleber: 6 mm | Re.R. | Kleber: 6 mm |

Assistance equipment

| | | | |
|---|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 399,16 |
| Alloy rim R L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Wing F L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Seat cover R R, Deformed, Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | | | 254,16 |





| | |
|--|------|
| Door moulding Lower F L, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|--------------------------|-------|
| Ceiling, Dirty, Cleaning | 25,00 |
|--------------------------|-------|



| | |
|---|--------|
| Window handle R R, Strained , E - Replace | 120,00 |
|---|--------|



| | |
|-------------------------------------|------|
| Bumper F R, Scratch(es), Acceptable | 0,00 |
|-------------------------------------|------|

No pictures to display